



June 10, 2008

## Mandatory VCX Vacuum Coolant Exchanger Inspection Bulletin - CHECKLIST

Please utilize this checklist to ensure compliance with the **VCX Vacuum Coolant Exchanger Inspection Bulletin**.

| <b>COMPLETED</b> | <b>INSTRUCTION</b>  |
|------------------|---|
| _____            | 1.) <b>Stop <u>all</u> VCX equipment usage immediately.</b>   |
| _____            | 2.) Read all material supplied in this notification package.  |
| _____            | 3.) Perform VCX tube visual inspection as identified in the VCX Inspection Procedure.   |
| _____            | 4.) Replace defective VCX Coolant Tube(s) as required.  |
| _____            | 5.) Install supplied VCX Coolant Tube Caution Label only on tubes passing visual inspection per enclosed instructions.  |
| _____            | 6.) Instruct <b>all VCX equipment users</b> of required inspection procedures before every equipment use.   |
| _____            | 7.) Implement a weekly confirmation process with your service technicians to verify all users follow published inspection procedures prior to each machine use. |
| _____            | 8.) Complete supplied verification post card & mail to RTI.   |
| _____            | 9.) Resume VCX equipment operation.   |

If you have any questions contact RTI Tech Support at 1-800-468-2321, press ext. 1.

RTI Technologies, Inc.  
10 Innovation Drive  
P.O. Box 3099  
York, PA 17402  
Direct: 717-840-0678  
800-468-2321