





Install Adapter on Port slightly more than finger tight

P/N 023-80147-00



Over-tightening will distort O-ring and cause Port to be blocked as shown



Insert a round tool or piece of 14 ga wire through O-ring during tightening to prevent the O-ring from deforming