



June 10, 2008

## **VCX Vacuum Coolant Exchanger Inspection Bulletin**

**To: All Owners and/or Users of RTI Technologies, Inc. VCX Vacuum Coolant Exchangers**

**Subject: VCX Stop Use - Notification**

**!URGENT! STOP USING ALL RTI VCX VACUUM COOLANT EXCHANGE EQUIPMENT IMMEDIATELY!**

**RESUME USE ONLY AFTER COMPLETE COMPLIANCE WITH ALL PROCEDURES IDENTIFIED IN THIS PACKAGE.**

Failure to follow mandatory RTI inspection procedures for VCX Vacuum Coolant Exchanger Equipment can result in coolant tube failure and possible personal injury during machine operation. Because of its importance, RTI is requiring you to:

- 1.) Read all of the enclosed VCX equipment information.
- 2.) Comply with all of the required procedures identified within this package.
- 3.) Sign and return the enclosed registration post card (postage prepaid) indicating your compliance with all requirements of this notification.

**Please be advised, the owner and/or user of this equipment assumes all risks associated with the operation of this equipment if RTI does NOT receive the completed and signed VCX registration card within 30 days of receipt.**

RTI Technologies, Inc.  
10 Innovation Drive  
P.O. Box 3099  
York, PA 17402  
Direct: 717-840-0678  
800-468-2321